



**synectics**  
SAFETY SPECIALISTS

The Region of Halton retained Synectics to conduct three in-service safety reviews across the Dundas Street corridor within the City of Burlington. The area, at the time of the study, had been subject to intense residential development over a number of years and the land use on the south side of Dundas Street, which is the current urban boundary of the Burlington, had been effectively built-out. As a result, the locations ranked high in terms of their collision history and potential for safety improvement.



Synectics carried out a detailed field investigation and office review. As a result of the review, treatments specific to each intersection were identified, ranging from changes to the signal phasing, clearing of sight triangles, rumble strips, up to the recommended installation of a red light camera.